




Alternator Stator

BIG TWIN

Stators replace stock units for models listed in molded (M) or unmolded (U) type.		
VT No.	Brand	Type
1981-88 Big Twin, Replaces 29965-81, 22 Amp		
32-0602	Volt Tech	M
32-8081	Volt Tech	U
32-9042	Accel	U
32-9041	Accel	M
1989-99 FXST, FLST; 1989-94 FLT, 1989-94 FXR, 1991-98 Dyna, Replaces 29970-88C, 32 Amp		
32-8083	V-Twin	U
32-8038	V-Twin	U
32-9045	Accel	U
32-0952	Plug Only	
1995-up FLT, Replaces 29969-95, 38 Amp, EFI		
32-0454	Volt Tech	U
1997-98 FLT, Replaces 29987-97		
32-0489	Volt Tech	U
32-9148	Accel	U
1999-01 FLT, FLHR Replaces 29987-99A		
32-0463	Volt Tech	U
2002-05 FLT, EFI, Carb, Replaces 29987-02,		
32-0470	OE	U
32-0872	Volt Tech	U
32-9350	Accel	U
2000 FXST/FLST, 1999-03 Dyna, Replaces 29951-99		
32-0464	Volt Tech	U
32-9145	Accel	U
2001-06 FXST/FLST, 2004-06 Dyna, Replaces 30017-01		
32-0529	Volt Tech	U
32-9146	Accel	U
2007 FLST-FXST, 2007 Dyna, Replaces 30017-07		
32-0868	Volt Tech	U
32-9147	Accel	U
2008-up FXST, Replaces 30017-08		
32-0953	Volt Tech	U
2006-up FLT, Replaces 29987-06		
32-0948	Volt Tech	U
32-9351	Accel	U
2008 FXST-FLST-Dyna, Replaces 30017-08		
32-0953		U



Stator Assembly Kit for Big Twins 1970-86 includes (2) 29988-73 locks, (1) 29954-71 retainer, (4) 2653 screws, (2) 2216W screws.

VT No.	#	OEM	Item
32-0598		Kit	Complete, all
32-0604	A	29954-71	Nylon Retainer, 10 pk.
32-0603	B	2216W	Screw, 10 pk.
37-8812	C	29988-73	Lock Plate, 10 pk.
37-8811	D	2653	Screw, Fillister, 7/8"
37-9003	D	2712	Screw, w/Lock Patch, 7/8"
37-9126		2720	Screw, w/Lock Patch, 1"

Deutsch Connector Sets

VT No.	Fits
32-1854	Stator (32-0529)
32-1855	Regulator (32-0898)

Warranty
All Electrical Components sold as individual pieces or in kits are covered under our warranty "Replacement Only" Provision. All electrical related item part numbers begin with a 32 prefix. No credit will be issued for these items as they are exchange only.