



# Rear Fender

All Fenders are STEEL!

# Strut Set

FRAME • FENDERS • TANKS

We suggest pre-fitting all component parts including engine and transmission assemblies before painting or final assembly of a frame, fender or tank.



50-0702



50-0743



50-0705



50-0762, 50-0774



50-0879



50-0761



50-0884



50-0884

Replica FLH Rear Fenders replace the original steel part. Taillight cut out and turn signal mounts noted.

VT No.	Application	Taillight	Type
50-0702	1958-76 FL	A	Flip
50-0705	1958-78 FL	B	Flip
50-0761	1973-78	C	Flip
50-0884	1973-78	C & D	Flip
50-0762	1979-84 OE	C & D	1 pc
50-0774	1979-84 Replica	C & D	1 pc
50-0879	1979-84 FLH	C	1 pc
50-0743	1979-84 Replica	B	1 pc

Accepts A Early 1955-72 type  
 Taillight B Tombstone or Beehive  
 Type C Late 1973-up large style  
 D Turn Signal Indents



50-1054



50-1053




50-0703

Rear Fender End. One-half of hinge is riveted to fender end.

VT No.	OEM	Type
50-1054	59699-39	1939-48 Rigid BT & 45
50-1053	59699-49	1949-57 Rigid BT & 45
50-0703	None	1958-78 No Cut Out
50-1006	59853-58	Hinge with Pin, 1958-78
50-0931	59851-39	Hinge with Pin, 1939-48
37-8840	59820-30	Hinge Pin



50-1072 Installed




50-1072



50-0901



50-0905



50-0900



50-0903



50-0902



50-0979



50-1080

Chrome Fender Strut Sets are available in smooth or stock style with signal and mount holes.

B-Smooth	A-Stock	OEM	Fits
50-0905	50-0900	59929-73	1973-83 FX-FXE
N/A	50-0979	As Above	Less turn signal holes
50-0906	50-1072	59923-58	1958-76 FLH w/5 holes
N/A	50-0901	As Above	With 7 holes
N/A	50-0902	59933-77	1977-84 FLH
50-0907	50-0903	59960-80	1980-85 FXWG
		59961-80	
N/A	50-1080	As Above	less turn signal holes



Strut Spacers replace 59938-72 on 1972-84 FX-FXE models, pair.


VT No. 37-9093



Chrome Allen Fender Strut Bolt Kits

include necessary allen head bolts, washers & nuts for fender mounting.

VT No.	Year/Model
37-9047	1980-85 FXWG
37-9048	1973-85 FX
37-9049	1958-84 FL w/o saddlebags/luggage rack



Chrome Rear Fender Support Mount Kit to replace original hardware for FLH.

VT No.	Year	Style
9638-30	1958-80	Acorn
8879-30	1958-80	Stock
2625-30	1958-80	Replica



8879-30